



NOTE: See connection diagram MG-3

ITEM	MATERIAL	QTY	STOCK #
c	Bolt, machine, 5/8" x req'd length	4	400
d	Washer, 3"	4	406001
an	Transformer, as req'd	2	0
p	Connectors, as req'd		0
av	Jumpers, #4 CU or equiv.		0
avi	Jumpers, insulated, as req'd		0
fi	Connector, hotline	2	5055

Gibson EMC

**TWO PHASE TRANSFORMER BANK,
CSP TRANSFORMERS (DEADEND POLE)**

AUG 2016
TN20

TRANSFORMERS

VG2-2