

Hurtman Rescue (Senior)

(Mean Time: 4 minutes)

Simulated Hot on 40' Pole / Rubber Gloves Are Required

1. Time starts at the judge's signal with the lineman outside the 11' circle around the pole. Climbing tools will be in the circle at the base of the pole.
2. The Rescue Manikin will hang on the opposite side of the pole from the neutral bracket with both ends of the safety strap going over the neutral. The OX Block will be hanging on the opposite side of the pole from the cutout on a Transformer Gin. There will be an extendo stick in the ground in a designated area. **(There will be a 2-point deduction for touching the extendo stick before time starts)**
3. At the judge's signal, the lineman will retrieve the extendo stick and open the cutout before climbing the pole then lay the fully retracted stick back in the designated area. After the cutout is open the lineman will proceed to put on all tools inside the 11' circle at the pole (this can be done without leather gloves or rubber gloves).
4. The OX Block & handline will be hanging on the opposite side of the pole from the cutout on a Transformer Gin above the mannequin. The lineman will then climb to the rescue position & split the handline and call "**HEADACHE**" before the hook or snap is dropped. The hook or snap must land in the 11' painted circle. If the hook or snap bounces out of the circle there will be no deduction as long as it lands inside the circle first.
5. The rescue manikin must be tied under the arms with three half hitches **(Eye splice marked with red tape 12" from the snap shall not be used as part of the hitches)**. The half hitch is the only acceptable knot.
6. When wrapping the handline around the friction bar of the Ox Block two clicks will be acceptable (manufacturer's recommendation). Before cutting the insert strap the gate of the Ox Block must be closed.
7. The Rescue Manikin must be lowered smoothly to the ground and land in the painted circle. (Contacting the pole is acceptable) If any part of the manikin is outside the painted circle there will be a 2-point deduction.
8. Time will stop when the lineman's first foot touches the ground in a safe and reasonable manner.
9. Exceeding 4 minutes to complete the event will result in a 10-point deduction.
10. Judging will start once the lineman enters the event and continue until that lineman exits the event.
11. **Note:** Using a length of 4" PVC conduit between the rope & the manikin, judges will evaluate the knot around the manikin.

Note: You will have 5 minutes to set-up prior to the event. Read guidelines (General Rules).



WORKING 1900 LBS.
LOAD LIMIT _____
(INCLUDES LIFT LINE AND PULL LINE IN PARALLEL)
HITCHER'S WIRE GLASS PRODUCTS, INC.

WARNING
To reduce the risk of serious personal injury or death:
•Inspect gin and replace all worn or damaged parts before each use.
•Always securely attach gin to pole. •Do not overload gin. (Be sure to include load calculation: weight of transformer, load on fall line and 4000 on tag lines.) •Do not strike or abuse gin. •Never apply side load to gin. •Do not lift loads over ground personnel.
•Never alter or modify gin in any way.









Team/Senior Hunt Man
75 x 75

1" = 20'



